

SEARCHED

Class	Sub.	Date	Exmr.
NOT CONCERNED TO SUBCLASS	SEARCH	3/21/01	BWB
372	45	Aug 25'01	BWB
	46		
UPDATED	ABOVE	FEB 5, 02	BWB
257	94		
	96		
	97		
	103		
	12-15		
	17, 22		

SEARCH NOTES (INCLUDING SEARCH STRATEGY)

EAST	Date	Exmr.
-enclosed	3/21/01	BWB
EAST enclosed	8/25/01	BWB
JOHN DARLING SAID THAT A RESPONSE HAS BEEN FILED, BUT A SUPPLEMENTAL COME IN & ASKED TO HOLD OFF EXAMINATION UNTIL AFTER 7/27/02	7/19/02 (INTERVIEW)	BWB
IDS #15: US 806/TYODA) Teaches claimed structure will lead to inadequate construction. - EP 988 teaches (Fig 1982) structure, - each labels as quick - NOT III-N, but ref says III-N can be used		

Amendments did NOT overcome 21563, BWB
Nakamura, No update search / /

INTERFERENCE SEARCHED

Class	Sub.	Date	Exmr.

BEST AVAILABLE COPY